

AC/DC CURRENT CLAMP 4100 WITH BAG

Article number: 111494

4100 TRMS AC/DC Clamp Meter, CAT IV/1,000 V, CAT III/1,500 V for maximum safety. AC/DC current measurement up to 400 A, voltage measurement up to 1,000 V AC and 1,500 V DC, AC/DC μ A measurement for HVAC. Measurement of resistance (up to 40 M), capacitance (10 nF to 100 μ F), and frequency (up to 10 MHz). TRMS, non-contact voltage detection (NCV), LPF, diode test, and continuity test. Features automatic shut-off and self-test function. Flashlight, backlit LCD display. Includes 2 test leads and 2 batteries. Includes carrying case.



Length (mm)	220 mm
Width (mm)	81 mm
Height (mm)	43 mm
Weight (kg)	0,3 kg

Attribute	Value
Display	digital
multiple display	No
With screen backlighting	Yes
measuring range selection	manuell/automatisch
Temperature measurement	No
continuity test	Yes
True RMS value measurement (TRMS)	Yes
measured value memory	Yes
Interface	No
Measurement category	CAT IV
Max. voltage measuring circuit category	1000 V
Capacitance measurement	Yes
Frequency measurement	Yes
Analog bar graph display	No
Current measurement range/AC	10 A - 400 A
Stromart	AC/DC
Voltage measurement, AC	Yes
Voltage measurement, DC	Yes
resistance measurement range	Yes
Power measurement	No
Leakage current measurement	No
harmonic measurement	No
Measurement in cable with forward and return conductor	Yes

CIMCO Werkzeuge GmbH & Co. KG
 Hohenagener Straße 1 – 5
 42855 Remscheid
 Telefon +49 2191 3718-01
 info@cimco.de • cimco.de

pliers opening	35 mm
Designed as an adapter for connection to multimeters	No
Current measurement range/DC	10 A - 400 A

GTIN: 4021103107041

CIMCO Werkzeuge GmbH & Co. KG
Hohenhagener Straße 1 – 5
42855 Remscheid
Telefon +49 2191 3718-01
info@cimco.de • cimco.de